



## ZEEL™ Frame Uninstall Instructions

**Tools needed: prybar, hammer, soft cloth, safety glasses**



### 1. Getting started

Tools needed: prybar, hammer, soft cloth, and safety glasses.

Place door or IG assembly on a table, or other flat, solid and stable surface, that is larger than the assembly.

### 2. Position the prybar

To start, use the flat chamfered end of the prybar.

*Tip:* We suggest placing a soft cloth under the prybar to prevent scratching the glass.



### 3. Wedge prybar between frame and glass

Prybar may need to be gently tapped with hammer to get under frame.

### 4. Push down on prybar to lift up frame


Push down on the prybar to break apart the tabs holding the frame together.

*Tip:* The easiest way to locate a tab is to begin in a corner.

Work slowly around the perimeter of the frame.

Break apart every tab one by one.

*Tip:* Move cloth around perimeter as you go to avoid damaging the glass.



### 5. Remove frame

Uninstall is now complete. Frame cannot be re-used.

**Please go to [zeel.odl.com/training](http://zeel.odl.com/training)  
to view uninstall video**